TOOL USE INSTRUCTION		
	TOOL NUMBER	TSN00953-300-B
RIVIAN	TITLE	SOCKET, AIRLINE FITTING 12MM
	REV - DATE	REV B - 04/22/2025

CONTENTS

OVERVIEW

SAFETY

INITIAL SETUP

TOOL USE INSTRUCTION

MAINTENANCE & STORAGE

SERVICE & REPLACEMENT PARTS

TROUBLESHOOTING

SYMBOL GLOSSARY

TOOL FUNCTION

USED FOR REMOVAL AND INSTALLATION OF 12MM VOSS AIRLINE FITTING ON R1 FRONT SUSPENSION.





SPECIFICATIONS

WEIGHT: 0.047 KG

Overall Dimensions: 17.5 MM X 50.0 MM

LABOR CODES


•185433010 - LINE ASSEMBLY, AIR SPRING (REMOVE AND REPLACE)


OTHER TOOLS REQUIRED

TSN00047-100-B: 1/4" DIGITAL TORQUE WRENCH

SOCKET DIMENSIONS

SQUARE DRIVE SIZE	SOCKET SHAPE	DRIVE SIZE	OVERALL LENGTH	OD
1/4"	6-POINT	12MM	50.00MM	17.50MM









WARNING

Do not perform procedure if tool is damaged or missing parts. Consult the Rivian Service Tool Catalog for replacement components.

Failure to follow guidelines outlined in this document could result in injury and/or property damage.

SAFETY GUIDELINES

1	 Risk of major injury if: Air suspension system isn't depressurized (up to 80 Psi) If the airline fitting is under-torqued 	Ţ
2	 Damage to the airline / airline fitting can occur if: Over-torqued Repeatedly tightened and loosened Kinking occurs in the hose 	
3	PPE Required: • Ear protection • Eye protection	



Depressurize the air suspension 1 system using RiDE Remove necessary items to gain access to the airline fitting 2



Check that the socket fits as shown.

Depending on the orientation of the airline fitting, it may need to be rotated to properly align.





1



Using the socket, extension and wrench, loosen fitting.

Once minimal force is required to turn the socket, remove fitting by hand.





2



3

When ready to be installed, hand tighten the airline fitting using the socket until it's unable to be tightened further

Next, using a digital torque wrench, torque the airline fitting

Refer to the service manual for the torque specification







MAINTENANCE & STORAGE

TASK	FREQUENCY
Inspect socket for damage. Do not use if socket is damaged	Prior to Each Use After Each Use
Return socket to its storage location	After Each Use



TROUBLESHOOTING

PROBLEM	SOLUTION
Socket isn't able to properly tighten/loosen the airline fitting	Inspect the tool to see if the following exists:
	Roundness/stripping
	• Wear/tear
	Significant discoloration
	If any of these issues are seen, replace the tool as needed





DANGER



CAUTION



CAUTION



PPE REQUIRED

REVISION LOG

REV	DATE	CHANGE DESCRIPTION
А	01/03/2023	Initial release
В	04/22/2025	Updated instructions to the latest TUI template and latest revision of the tool.

