

TSN01389: Washer Fluid Reservoir Line Cap - Service Tool

PURPOSE:

This tool is used on R1 MY 2025> for Front Fascia removal to plug the washer fluid line (used for front fascia camera cleaning).

This can also be used in any instance that the washer fluid line needs to be disconnected from a connection point or from the washer reservoir and you want to prevent losing washer fluid in the process.



LABOR CODE:

5246- Front Bumpers

OTHER TOOLS REQUIRED:

Pocket screw driver or small pick tool

PRIOR TO USAGE:

i Visual Inspection

1. Visually inspect tool for any damage or broken components
2. If any damage is present, replace assembly before performing the procedure
3. If label is missing, be sure to order a new assembly

⚠ CAUTION: Do not perform procedure if any equipment is missing or damaged. Contact tooling team with any questions or requests for replacement parts. ServiceToolEngineering@rivian.com

TOOL USAGE:

STEP	DIRECTIONS	VISUAL AID
1	<p>Locate washer line going to washer reservoir coming from the Front Fascia.</p> <p>i This is located on the Passenger side of the vehicle behind the front wheel liner.</p>	
2	<p>Disconnect at the coupler point.</p> <p>You may lose a small amount of fluid during this process! Be sure to have an absorption rag handy.</p> <p>i You will need to use a pocket screw driver or a small pick to slide the coupler lock back. This will allow you to disconnect the line (fascia side) from the washer reservoir line.</p>	



3

Once the coupler connection is disconnected, attach **TSN01389-300 WASHER FLUID RESEVOIR CAP** onto the washer line on the reservoir side.



4

When you are done with the cap, disconnect the same way you disconnected the washer line from the Fascia side (slide silver coupler lock back) and re-connect the fascia washer line back to the washer reservoir line.

 Installation is the reverse of removal